



**Quality Petroleum Equipment  
Solutions for Over 25 Years**

\*\*\*\*\*

**VMI-3300 & VMI-3300\FL  
3" In-line Check Valves**



VMI-3300

**VMI-3300 In-line Check Valve, 15 PSI Relief  
3" Male NPT Inlet, 3" Female NPT Outlet**

\*\*\*\*\*

**VMI-3300\FL In-line Check Valve, 15 PSI Relief  
3" Male NPT Inlet, Flanged Outlet**

\*\*\*\*\*

When a Big Flo (3hp or 5hp) STP check valve fails, it is an expensive fix. A two-man crew and a crane are required to pull the STP and access the check valve. Service companies have estimated this fix starting at \$1,500.

To prevent line leak detection (LLD) false alarm nuisance problems, the LLD requires a functioning check valve upstream of itself. This does not mean the the LLD must have functioning check valve in the STP head.

The VMI-3300 installs in the discharge of the STP, providing a very economical solution and an easy to access, replaceable pressure relief.

Compatible with any fuel: Typical gasoline, diesel, kerosene, and alcohol & biodiesel blends up to neat concentrations.

**Vaporless Manufacturing, Inc.  
8700 East Long Mesa Drive, Prescott Valley, Arizona 86314  
800-367-0185 928-775-5191 Fax: 928-775-5309  
Email: [vmi@vaporless.com](mailto:vmi@vaporless.com) Web Site: [www.vaporless.com](http://www.vaporless.com)**